

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 04/01/2003

DEN02LA103 File No. 12762	09/08/2002	Mead, CO	Aircraft Reg No. N551SA	Time (Local): 09:30 MDT		
Make/Model:	Adler / SA-1			Fatal	Serious	Minor/None
Engine Make/Model:	Rotax / 912WLS		Crew	1	0	0
Aircraft Damage:	Destroyed		Pass	0	0	0
Number of Engines:	1					
Operating Certificate(s):	None					
Type of Flight Operation:	Personal					
Reg. Flight Conducted Under:	Part 91: General Aviation					
Last Depart. Point: Broomfield, CO				Condition of Light: Day		
Destination: Local Flight				Weather Info Src: Weather Observation Facility		
Airport Proximity: Off Airport/Airstrip				Basic Weather: Visual Conditions		
				Lowest Ceiling: None		
				Visibility: 10.00 SM		
				Wind Dir/Speed: 140 / 004 Kts		
				Temperature (°C): 24		
				Precip/Obscuration: None / None		
Pilot-in-Command	Age: 51			Flight Time (Hours)		
Certificate(s)/Rating(s)				Total All Aircraft: 280		
Private; Single-engine Land; Gyroplane				Last 90 Days: 44		
Instrument Ratings				Total Make/Model: 44		
None				Total Instrument Time: 3		

Witnesses observed "a rotor or a wing" separate from the gyroplane, and the gyroplane then descended and impacted terrain. According to the deputy's report, a rotor blade was found about 150 feet north of the point of impact, and other debris was strewn to the southwest. The co-builder of the accident gyroplane, who was also a close friend of the pilot, contacted three gyroplane experts: the designer of the SA-1 Dominator and President of Rotor Flight Dynamics; a gyroplane aerodynamicist; and the designer of another gyroplane. They examined the wreckage and compiled both a factual and analytical report. The following is based on the factual portion of the report. The separated rotor blade was bowed upward and had fractured about 2 feet from the tip. The fracture was consistent with positive overload. There was orange paint and primer transfer marks on the top and upper leading edge (the tail cone was painted orange). The attached rotor blade was also bent upward. The propeller blades exhibited no strike marks. The rotor head and hub bar were intact. The hub bar, normally bent 2.5 degrees upward, was bent approximately 10 degrees upward. The roll pillow blocks bore evidence of hammering and were mushroomed. The pitch stops were similarly damaged. In the analytical portion of the report, the necessity of maintaining blade loading at all times in order to maintain main rotor blade rotation was noted. The fracture on the separated main rotor blade was in "a purely upward bending moment which could only have occurred if the blade rpm had dramatically slowed...If totally unloaded, the blade rpm can deteriorate as fast as 120 rpm/sec." Normal rotor blade rpm is 320 to 400 rpm. If rotor blade rpm were allowed to drop, increasing the velocity of air moving through the rotor system, severe blade "flapping" would result as evidenced by the pounding and mushrooming of the roll pillow blocks and bending of the hub bar on the rotor head. A toxicological test revealed 2.024 (ug/mL, ug/g) paroxetine in the blood and liver. The drug is an antidepressant and contraindicated for flight. The pilot's personal physician prescribed the drug for the treatment of fibromyalgia, a condition manifested by muscle soreness. Adverse effects of the drug include drowsiness, muscle weakness, agitation, and tremors.

Brief of Accident (Continued)

DEN02LA103				
File No. 12762	09/08/2002	Mead, CO	Aircraft Reg No. N551SA	Time (Local): 09:30 MDT

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: MANEUVERING

Findings

1. (C) ROTOR RPM - NOT MAINTAINED - PILOT IN COMMAND
 2. USE OF INAPPROPRIATE MEDICATION/DRUG - PILOT IN COMMAND
 3. (C) ROTOR SYSTEM,MAIN ROTOR - OSCILLATION
-

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Findings

4. TERRAIN CONDITION - GRASS
5. TERRAIN CONDITION - OPEN FIELD

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
the pilot's failure to maintain main rotor rpm, resulting in blade flapping, subsequent blade contact with the airframe, and loss of control.